

**H046 Rękawice Bawełniane Przeciwpotne****ZDJĘCIA**

Wykonanie i badania wyrobu zgodnie z normą: PN-EN ISO 21420:2020-09

Rozmiar uniwersalny  
Długość: 240mm ± 3mm

**OPIS**

Rękawice dziane, pięciopalcowe, wykonane w 100 % z bawełny w kolorze białym. Rękawice posiadają ściągacz zapobiegający zsuwaniu się rękawic z dłoni.

**ZASTOSOWANIE**

Rękawice bawełniane mają za zadanie wchłaniać wilgoć i stanowią zabezpieczenie dłoni przed nadmiernym poceniem podczas wykonywania prac pod napięciem.

**PRZECHOWYWANIE I KONSERWACJA**

Rękawice przechowywać w etui. Zabrudzone rękawice wyprać w ciepłej wodzie (do 50 °C) z dodatkiem delikatnego detergentu a następnie wysuszyć w temperaturze nie przekraczającej 60 °C.

**SPRAWDZENIE**

Przed każdym rozpoczęciem pracy należy dokonać oględzin. Kontrolę okresową, polegającą również na oględzinach przeprowadzać raz na rok.

Oględziny obejmują sprawdzenie:

- o braku widocznych uszkodzeń rękawic

Rękawice uszkodzone i silnie zużyte (rozdarcia, przetarcia) lub zabrudzone nie mogą być użyte w pracach pod napięciem. W przypadku zawilgocenia rękawice należy dokładnie osuszyć przed użyciem.

**UWAGA!**

W przypadku wątpliwości po przeprowadzeniu oględzin, rękawice powinny zostać wycofana z użytkowania w pracach pod napięciem.

**H046 Rękawice Bawełniane Przeciwpotne****CZĘSTOTLIWOŚĆ BADAŃ**

Sprawdzenie przed użyciem i kontrolę okresową przeprowadzać zgodnie z poniższą tabelą.

	<b>SPRAWDZENIE</b>	<b>KONTROLA OKRESOWA</b>
Przez kogo	Kierujący zespołem	Dozór
Kiedy	Przed każdorazowym użyciem	Raz na rok*
W jaki sposób	Wzrokowo (ogłędziny)	Wzrokowo (ogłędziny)

\*jeżeli instrukcja organizacji prac pod napięciem nie stanowi inaczej

**H046 Sweat Absorbing Cotton Gloves****PHOTOS**

Manufacture and testing of the product in accordance with the standard: PN-EN ISO 21420:2020-09

Universal size  
Length: 240mm ± 3mm

**CHARACTERISTICS**

Knitted, five-finger gloves made of 100% white cotton. The gloves feature an elastic cuff to prevent slipping off the hands.

**APPLICATION**

The cotton gloves are designed to absorb moisture and provide protection against excessive sweating during live working.

**STORAGE AND MAINTENANCE**

Store the gloves in a case. Wash soiled gloves in warm water (up to 50°C) with a mild detergent and then dry at a temperature not exceeding 60°C.

**EXAMINATION**

Before each use the gloves must be visually inspected. Conduct periodic inspections annually, including visual checks. Inspections involve verifying:

- no visible damage or soiling of the gloves.

Gloves that are damaged (tears), heavily worn (abrasions, rips) or soiled must not be used for live work. In case of dampness, the gloves should be thoroughly dried before use.

**ATTENTION!** If there are doubts after conducting inspections, the gloves should be withdrawn from use in tasks under voltage.

**H046 Sweat Absorbing Cotton Gloves****FREQUENCY TESTS**

Perform pre-use checks and periodic inspections according to the table below

	CHECK PERIODIC INSPECITON	CHECK PERIODIC INSPECITON
Who	Manager of team	Supervision
When	Before each use	Once a year*
How	Visual inspection	Visual inspection

\* Unless instructions say otherwise